


Ordinate scales are % relative standard deviation and nu-bar.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scales are % relative standard deviation and nu-bar.

Abscissa scales are energy (eV).











Ordinate scales are % relative standard deviation and nu-bar.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scales are % relative standard deviation and mu-bar.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scales are % standard deviation and spectrum/eV.

Abscissa scales are energy (eV).






Correlation Matrix