

Ordinate scales are % relative standard deviation and nu-bar.

Abscissa scales are energy (eV).









Ordinate scales are % relative standard deviation and nu-bar.

Abscissa scales are energy (eV).





Correlation Matrix





Ordinate scales are % relative standard deviation and nu-bar.

Abscissa scales are energy (eV).





Correlation Matrix





Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).





Correlation Matrix





Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).





Correlation Matrix





Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).





Correlation Matrix





Ordinate scales are % relative standard deviation and barras.

Abscissa scales are energy (eV).





Correlation Matrix





Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).





Correlation Matrix





Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).





Correlation Matrix





Ordinate scales are % relative standard deviation and mu-bar.

Abscissa scales are energy (eV).





Correlation Matrix





Ordinate scales are % standard deviation and spectrum/eV.

Abscissa scales are energy (eV).



Correlation Matrix