



$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Ni}(n,\text{tot.})$





Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.




Correlation Matrix



$\sigma$  vs. E for  $^{60}\text{Ni}(n,\text{tot.})$


$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Ni}(n,\text{el.})$





Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Ni}(n,\text{inel.})$




Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).



Correlation Matrix




$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Ni}(n,2n)$




Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).



Correlation Matrix




$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Ni}(n,\gamma)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix

